

Plant Hazard and Risk Assessment

OWNER/INSPECTION DETAILS

Inspection #5138

Date	04/09/2023
Provided for	XPower
Plant Make & Model	Komatsu PC55MR-3 5 ton Excavator
Identification No.s	1MH2NE. Serial 19536
Hour Meter Reading	4053
Inspection Done at	Coburg North

Assessment Conducted By

Steersafe Training and Assessment ABN 84 137 032 681 Scott Haynes

Certificate IV Training & Assessment TAA40104
Certificate No 1678

Phone: 0418 536 870

CONTENTS

OWNER DETAILS	1
ACKNOWLEDGMENT AND AGREEMENT	3
PLANT HAZARD & RISK ASSESSMENT	4
NOISE ASSESSMENT	11
DISCLAIMER	12

AGREEMENT

THIS AGREEMENT is made on 4th day of September, 2023

and is made between:

SCOTT HAYNES of Steersafe Training and Assessment, and

Stan Miriklis of XPower

The owner/operator agrees to engage Scott Haynes to perform Risk Assessment on the basis of agreement to the following disclaimer.

DISCLAIMER

"Mobile Plant" means the mobile plant, vehicle or equipment described in the assessment and inspected by the assessor.

This assessment is based upon information provided to the assessor up until the date of the assessment. If any modification, alteration or addition is made to the mobile plant following that date, this assessment is null and void and cannot be relied upon for any purpose. In particular, this assessment will then provide no assurance that the mobile plant complies with the *Occupational Health and Safety Regulations 2017* or any regulation amending or replacing those regulations. The owner and operator of the mobile plant must conduct regular inspections and maintain the mobile plant at regular intervals. If any alteration or addition is made to the mobile plant, such alterations or additions must be recorded in writing and retained by the owner and operator. The mobile plant will then need to be re-assessed.

At all times it is the responsibility of the owner and operator of the mobile plant to maintain the mobile plant according to the *Occupational Health and Safety Regulations 2017* and all other applicable legislation and regulations. The assessor is not and shall not be liable for the mobile plant complying with the *Occupational Health and Safety Regulations 2017* or any regulation amending or replacing those regulations. This assessment does not pass any responsibility for such compliance to the assessor, and does not in any way exempt the owner and operator from the continuing responsibility for such compliance. The owner and operator agree to indemnify the assessor against all liability of whatever kind in relation to the mobile plant assessed.

This assessment will be conducted by a qualified workplace assessor. This assessment will not be conducted by a qualified mechanic nor a roadworthy assessor, and no responsibility is assumed by the assessor for any mechanical malfunction of the mobile plant nor lack of roadworthiness.

This assessment identifies risks in relation to the mobile plant only, and does not assess risks in relation to the site where the mobile plant is to be used. A job safety and environmental analysis is required to identify such site risks and should be reviewed by the owner and operator prior to commencement of work on site.

ACKNOWLEDGEMENT AND AGREEMENT

I confirm that I have read and understood the disclaimer and notes set out about and agree with all terms

Name: Stan Miriklis Signed:

Company/Organization: XPower

Date: 04/09/2023

Plant Hazard & Risk Assessment

Hazard	Risk	Control	Control in place	Action Required																																																									
1. CRUSHING Can anyone be crushed by:																																																													
(a) material falling off the plant		Operator licensed to operate plant	✓	None																																																									
		Decals fitted	✓	None																																																									
(b) uncontrolled or unexpected movement of the plant or its load		Reverse alarm fitted	✓	None																																																									
		Horn fitted	~	None																																																									
		Decals fitted	~	None																																																									
		Reverse swing/ warning lights	~	None																																																									
		Flashing beacon	~	None																																																									
		Non slip pedals	✓	None																																																									
	H I G H	нібн	H I G H	нібн	Mirrors fitted	~	None																																																						
					H 1 G H	HIGH	HIGH	HIGH	H 1 G H		H I G H			-	HIGH	нгсн	HIGH	-		Parking brake operational	~	None																																							
(c) difficulty in slowing, stopping or immobilising the plant]				7]		Service brake operational*	~	None																								
										Regular maintenance of plant as recorded	✓	None																																																	
(d) the plant tipping or rolling over											ROPs approved structure or cabin	✓	None																																																
											<u> </u> 	<u> </u> -	<u> </u> -	<u> </u> -	<u> </u> 	<u> </u> 	ROPs sticker fitted	✓	None																																										
(e) being thrown off or under the plant																	1	Doors fitted	✓	None																																									
		ROPs approved structure or cabin	✓	None																																																									
																															•					· · · · · · · · · · · · · · · · · · ·	· •	- I	· · · · · · · · · · · · · · · · · · ·				· •		· •								· •	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	·	Seat belt fitted	✓	None
		Cabin fully enclosed	✓	None																																																									

^{*}Brakes are checked for function, and not for brake adjustment or brake wear. This is solely the responsibility of the owner/operator.

Hazard	Risk	Control	Control in place	Action Required					
(f) being trapped between the plant, materials or a fixed structure.		Reverse alarm fitted	✓	None					
		Neutral start switch	✓	None					
		Horn fitted	~	None					
		Decals fitted	✓	None					
	нібн	Flashing beacon	✓	None					
		Non slip pedals	✓	None					
							Mirrors fitted	✓	None
g) attachments. ie buckets, blades, drills, etc		Pins and bushes in good condition	✓	None					
h) any other factors not mentioned			✓	None					
2. SHEARING Can anyone's body parts be cut off or	sheared:								
(a) between two parts of the plant		Decals fitted	✓	None					
		Burst protection valves fitted where required	~	None					
(b) between a part of the plant and a work piece or structure		Reverse alarm fitted	✓	None					
	нібн	Swing lights fitted where required	✓	None					
		Horn fitted	✓	None					
c) any other factors not mentioned			~	None					

Hazard			Ri	isk			Control	Control in place	Action Required
3. STRIKING Can anyone be struck by moving obje	ects du	ie to:							
a) uncontrolled or unexpected movement of the plant or material							Reverse alarm fitted	✓	None
							Reversing warning decal fitted	~	None
							Flashing beacon on plant	~	None
						Horn fitted	✓	None	
							Controls/levers identified	✓	None
b) the plant, or parts of the plant disintegrating		Е	D	т	TT .	U M	Regular maintenance of plant as recorded	~	None
		Ľ	D	1	0 .		Decals fitted	✓	None
							Guards fitted as required	~	None
c) the mobility of the plant						Reverse alarm fitted	✓	None	
							Decals fitted	✓	None
							Flashing beacon	✓	None
d) any other factors not mentioned								✓	None
4. ENTANGLEMENT Can anyone be injured by:									
a) hair, clothing or any other items they are wearing or attached to them, become entangled							Guards fitted as required	✓	None
in the moving parts of the plant or materials on the plant?	М	E	D	I	U	M	Warning decals for moving parts	✓	None
b) any other factors not mentioned								✓	None

Hazard	Risk	Control	Control in place	Action Required
5. CUTTING, STABBING & PUNCTUL Can anyone be injured by:	RING			
a) contact with sharp or moving parts on the plant		Guards fitted as required	~	None
		Decals fitted	~	None
b) the plant, or parts of the plant disintegrating		Regular maintenance of plant as recorded	>	None
c) uncontrolled or unexpected movement of the plant or material		Reverse alarm fitted	✓	None
	M E D I U M	Reversing warning decal fitted	>	None
		Flashing beacon	✓	None
		Horn fitted	~	None
		Brake lights and indicators	~	None
		Rear swing/reverse warning lights	~	None
d) any other factors not mentioned			✓	None

Hazard			R	isk			Control	Control in place	Action Required
6. TRIPPING, SLIPPING OR FALLING Can anyone using or in the vicinity of the plant, trip, slip, or fall due to									
a) slippery or uneven work surfaces							Non slip steps and work area	~	None
b) inadequate steps and handrail to enter and exit plant							Non slip steps and handrail to ensure 3 points of contact to enter and exit plant	✓	None
c) inadequate rail or other suitable edge protection	M	E	D	I	U	M	Handrail or edge protection in place where required	~	None
d) obstacles in the vicinity of the plant. E.g.: oil spill or plant attachments							No visible signs of fluids leaking from plant	~	None
							Work area free from debris and work materials	~	None
d) any other factors not mentioned								✓	None
7. ERGONOMIC Can anyone be injured by: a) badly designed or damaged seating							Driving seat in good		
a) badis designed of damaged seating							condition		None
b) inhibited body posture or the need for excessive effort							Adjustable seat position	<u> </u>	None
							Adjustable driving controls	✓	None
c) inadequate lighting	M	E	D	I	U	M	Adequate lights in and outside of cabin	✓	None
d) unsafe entry and exit points							Non slip steps and handrail to ensure 3 points of contact to enter and exit plant	~	None
e) any other factors not mentioned								✓	None

Hazard			Ri	isk			Control	Control in place	Action Required
8. ELECTRICAL Can anyone be injured or burnt from electrical shock by:									
a) exposed and damaged battery or leads							Guards around battery or wiring	✓	None
							Regular maintenance of plant as recorded	✓	None
							Decals fitted	✓	None
b) the plant contacting live electrical conductors	М	E	D	Ι	U	M	JSAs on site and spotters when operating near overhead wires	~	None
c) damaged electrical wiring, switches or cables							Regular maintenance of plant as recorded	✓	None
d) any other factors not mentioned								✓	None
9. BURNS Can anyone be burnt by: a) contact with exhaust Guards around									
							exhaust Decals fitted	<u> </u>	None
								<u> </u>	None
	M	E	D	I	U	M	Exhaust mounted away from easy access	✓	None
b) fire in the plant							Regular maintenance of plant as recorded	~	None
							Fire extinguisher supplied in plant	<u> </u>	None
c) any other factors not mentioned								✓	None
10. HIGH PRESSURE AND EXPLOSION Can anyone be injured by:									
a) high pressure fluid	M	E	D	T	T T	M	Regular maintenance of hydraulic hoses and couplings as recorded	~	None
b) explosions caused by gas, vapours, liquids or other substances	M	Ľ	ע	1	U	IVI	All seals and tanks in good working order	✓	None
c) any other factors not mentioned								✓	None

Hazard	Risk						Control	Control in place	Action Required
11. SUFFOCATION/ASPHYXIATION Can anyone suffer or become ill from									
a) lack of oxygen within the plant cabin							Adequate ventilation (windows)	✓	None
							Air conditioning	>	None
b) fumes, toxic gases or vapours within the plant cabin							Exhaust in good operating condition	~	None
	м	E	D	I	T T	M	Door and window seals in good condition	~	None
c) dust within the plant cabin	м Е	ı.	D	1	U	IVI	Door and window seals in good condition	~	None
d) overheating within the plant cabin							Adequate ventilation (windows)	✓	None
							Air conditioning	~	None
e) any other factors not mentioned								~	None
12. OTHER HAZARDS Can anyone be injured or become ill f	rom:								
a) excessive noise							Hearing protection supplied N.B. See noise level test for more detail	~	None
b) vibration							Excessive Vibration	✓	None
c) excessive temperatures in cabin	M	E	D	Ι	U	M	Heater and air conditioner	✓	None
							Adequate ventilation and sealing doors and windows	>	None
e) any other factors not mentioned								✓	None
13. DOCUMENTATION Has information been provided on the following:									
a) daily pre start inspection check list							Pre start provide	✓	
b) service and maintenance records	,,		г.				Service history provided	~	None
c) plant operation manual	M	Е	D	Ι	U	M	Plant Manual provided	✓	
d) suitable licence for operation of the plant							Licence provided	✓	None

NOTE

High risk denotes a possible or probable occurrence and possible death, or life threatening injury, or permanent disability without the use of controls.

Medium risk denotes unlikely or possible occurrence and possible injury without the use of controls.

NOISE ASSESSMENT

The noise level reading shall be taken at exhaust level, and within 1050mm of the exhaust emission. The reading will be taken at idle and at "Engine Speed at Maximum Power". This procedure is in accordance with the *Environment Protection (Vehicle Emissions) Regulations 2003*.

A further reading shall then be taken from the cabin of the truck.

The sound meter used for this assessment is a Digitech QM-1589, Serial No 10060748 in accordance with the *Environment Protection (Vehicle Emissions) Regulations 2003*.

Plant Details	Komatsu PC55MR-3 5 ton Excavator
Identification No.	1MH2NE. Serial 19536
Background Noise	dBA : 47.8
Noise in Cabin at Idle	dBA: 68.8
Noise in Cabin at Maximum Power	dBA: 72.3
Noise at Idle	dBA : 74.8
Noise at Maximum Power	dBA: 78.6

DISCLAIMER

"Mobile Plant" means the mobile plant, vehicle or equipment described in the assessment and inspected by the assessor.

This assessment is based upon information provided to the assessor up until the date of the assessment. If any modification, alteration or addition is made to the mobile plant following that date, this assessment is null and void and cannot be relied upon for any purpose. In particular, this assessment will then provide no assurance that the mobile plant complies with the *Occupational Health and Safety Regulations 2017* or any regulation amending or replacing those regulations. The owner and operator of the mobile plant must conduct regular inspections and maintain the mobile plant at regular intervals. If any alteration or addition is made to the mobile plant, such alterations or additions must be recorded in writing and retained by the owner and operator. The mobile plant will then need to be re-assessed.

At all times it is the responsibility of the owner and operator of the mobile plant to maintain the mobile plant according to the *Occupational Health and Safety Regulations 2017* and all other applicable legislation and regulations. The assessor is not and shall not be liable for the mobile plant complying with the *Occupational Health and Safety Regulations 2017* or any regulation amending or replacing those regulations. This assessment does not pass any responsibility for such compliance to the assessor, and does not in any way exempt the owner and operator from the continuing responsibility for such compliance. The owner and operator agree to indemnify the assessor against all liability of whatever kind in relation to the mobile plant assessed.

This assessment has been conducted by a qualified workplace assessor. This assessment was not conducted by a qualified mechanic nor a roadworthy assessor, and no responsibility is assumed by the assessor for any mechanical malfunction of the mobile plant nor lack of roadworthiness.

This assessment identifies risks in relation to the mobile plant only, and does not assess risks in relation to the site where the mobile plant is to be used. A job safety and environmental analysis is required to identify such site risks and should be reviewed by the owner and operator prior to commencement of work on site.

ACKNOWLEDGMENT AND ACCEPTANCE

I confirm that I have read and understood the disclaimer and notes set out above and agree with all terms.

I also acknowledge I have received the completed Risk Assessment for the aforementioned Mobile Plant

Name: Stan Miriklis Company/Organisation: XPower

Signed: Date: 04/09/2023